




RAILWAY

design Giacomo Moor

Storage unit, available in the high and low versions, consisting of 22 mm thick honeycomb-core shelves with solid fir frame and internal honeycomb, and blockboard shoulders and back; all elements are veneered in the variants charcoal dyed oak, multilaminar wood veneer Striped Grey, Stone Oak®. Door in MDF with top and bottom edges in V-shaped solid wood, available veneered in the same finish as the cabinet


(shelves, shoulders and back) or glossy lacquered in cream white RAL9001, wine red RAL3005, stone grey RAL7030, quartz grey RAL7039. Steel door runners 15x15 mm square section, epoxy painted black anodik. Aluminium legs 15x15 mm, epoxy painted black anodik. Adjustable feet with black PVC cap.

Steel door runners and Legs




Anodik
Black Painted
Steel

Shelves



Charcoal-dyed
Oak




Stone Oak®




Striped Grey

Door



Charcoal-dyed
Oak



Stone Oak®



Striped Grey



Lacquered
Glossy RAL
9001 White
Cream



Lacquered
Glossy RAL
3005 Red Wine




Lacquered
Glossy RAL
7030 Stone
Grey



Lacquered
Glossy RAL
7039 Quartz
Grey

Technical Drawings



Note

Stone Oak®: this wood owes its particular coloring to an entirely natural process. Because of this, some slabs may look more brown than others. Our commitment is to provide you a high quality product; any differences in color should not be considered as defects.

Striped Grey: it is a decorative multilaminar wood veneer, always finished with a transparent acrylic painting, which features exclusive patterns reproducing the natural characteristics of wood. We would like to remind you that, being a natural and living wooden material, it may present non-homogeneous colour shades, which are peculiarities of the material itself.

On request, an additional protective (acrylic solvent) painting is available for the Stone Oak® finishing only. It should be noted that this additional coating slightly changes the natural color and texture of the surface. Although this supplementary painting increases the surface resistance, it is still a natural material; therefore small superficial stains, due to oil or other substances, have to be promptly removed, before being absorbed in depth by the wood. Thus, we recommend regular care and maintenance.



